

| | Engine Flush & Oil Change Part Code 5777 | Diesel Injector Cleaner Part Code 7627 | Diesel Particulate Filter Part Code 7795 | Diesel Power Ecomax Part Code 6206 | Stop Leak Part Code 5619 | Extra Cool Part Code 5547 |
|--|---|---|---|---|--------------------------------|---------------------------------|
| Oil & Transmission | | | | | | |
| Routine Maintenance - Every Service | ● | | | | | |
| Dirty or Contaminated Oil System | ● | | | | | |
| Diesel Dilution | ● | ● | ● | ● | | |
| Oil Leaks | | | | | ● | |
| Piston Rings & Crown | ● | | | ● | | |
| Cooling System | | | | | | |
| Cooling Problems | | | | | | ● |
| Diesel Fuel System Problem | | | | | | |
| Fuel System Clean & Routine Maintenance | | | | ● | | |
| Reduced MPG | | ● | | ● | | |
| Injector Cleaning Service | | ● | | | | |
| Faulty Injectors | | ● | | | | |
| Fuel Filter | | | | ●x2 | | |
| Exhaust Gas Aftertreatment Problems - DPF, EGR, Turbo, Sensors, Catalytic Converter | | | | | | |
| MOT Emissions Failure | | ● | | | | |
| Black Exhaust Smoke | | ● | | | | |
| Blue Exhaust Smoke | ● | | | ● | | |
| Reduced Compression | ● | | | ● | | |
| DPF Light On | ● | ● | ● | ● | | |
| DPF Replacement | ● | ● | ● | ● | | |
| EGR Problems | ● | ● | ● | ● | | |
| EGR Replacement | ● | ● | ● | ● | | |
| Turbo Problems | ● | ● | ● | ● | | |
| Turbo Replacement | ● | ● | ● | ● | | |
| Performance Restoration Clean | ● | ● | ● | ● | | |
| 5th Injector Contamination | ● | ● | ● | ● | | |
| Manifold Contamination (swirl flap) | ● | ● | ● | ● | | |